


FIG. 1B







FIG. 2B



Transmission Test

Sample 9MHz Immersion Parts → Backing Material Effects

(pitch and catch)

Time Response

Vbias = 90V


Vac = 10V 30ns pulse

2mm separation

No backing material

Medium = water


FIGURE 4A



2-way Insertion Loss

-6dB BW = 78.82%

FIGURE 4B



Time Response

Vbias = 90V


Vac = 10V 30ns pulse

2mm separation

With backing material

Medium = water

FIGURE 4C



2-way Insertion Loss

-6dB BW = 84.02%

FIGURE 4D

